

Pre-Demolition Asbestos Survey

Proposed Circle K

Flora Vista, New Mexico

January 29, 2013

Terracon Project No. 66137030



Prepared for:

Circle K Stores, Inc.
Tempe, Arizona

Prepared by:

Terracon Consultants, Inc.
Albuquerque, New Mexico

Offices Nationwide
Employee-Owned

Established in 1965
terracon.com

Terracon

Geotechnical ■ Environmental ■ Construction Materials ■ Facilities

January 29, 2014



Circle K Stores, Inc.
1130 West Warner Road, Building B
Tempe, Arizona 85284

Attn: Mr. Bill Bunch
P: [602] 728 6639
F: [602] 307 6639
E: wbunch@CircleK.com

Re: Pre-Demolition Asbestos Survey
Proposed Circle K Store
SWC of Highway 516 and Country Road 350
Flora Vista, San Juan County, New Mexico
Terracon Project No. 66137030

Dear Mr. Bruch:

The purpose of this report is to present the results of an asbestos survey performed on January 14, 2014 at the above referenced building in Flora Vista, New Mexico. This survey was conducted in general accordance with our proposal dated November 1, 2013. We understand that this survey was requested due to the planned demolition of the structure.

Friable asbestos-containing materials were identified. Please refer to the attached report for details.

Terracon appreciates the opportunity to provide this service to Circle K Stores, Inc. If you have any questions regarding this report, or if you need assistance with project oversight and sampling during demolition or renovation of this building, please contact the undersigned at 505-797-4287.

Sincerely,
Terracon Consultants, Inc.

Prepared By:

A handwritten signature in blue ink, appearing to read 'Julie A. Smith'.

Julie A. Smith
Environmental Scientist

Reviewed By:

A handwritten signature in blue ink, appearing to read 'Mitch Reiber'.

Mitch Reiber
Senior Project Industrial Hygienist

TABLE OF CONTENTS

	Page
1.0 INTRODUCTION	1
1.1 Project Objective	1
2.0 BUILDING DESCRIPTION	1
3.0 FIELD ACTIVITIES	2
3.1 Visual Assessment	2
3.2 Physical Assessment.....	2
3.3 Sample Collection.....	2
3.4 Sample Analysis	3
4.0 REGULATORY OVERVIEW	3
5.0 FINDINGS AND RECOMMENDATIONS	3
6.0 GENERAL COMMENTS	4

APPENDIX A ASBESTOS SURVEY SAMPLE SUMMARY

APPENDIX B CONFIRMED ASBESTOS-CONTAINING MATERIALS

APPENDIX C ASBESTOS ANALYTICAL LABORATORY DATA

APPENDIX D CERTIFICATIONS

**PRE-DEMOLITION ASBESTOS SURVEY REPORT
PROPOSED CIRCLE K STORE
SWC of HIGHWAY 516 and COUNTRY ROAD 350
FLORA VISTA, NEW MEXICO**

Terracon Project No. 66137030

Date: January 29, 2014

1.0 INTRODUCTION

Terracon conducted an asbestos survey of the vacant building located at the southwest corner of Highway 516 and Country Road 350, Flora Vista, New Mexico. The survey was conducted on January 14, 2014 by an AHERA-accredited asbestos inspector in general accordance with Terracon Proposal No. P6613-0298 dated November 1, 2013. Interior and exterior building components were surveyed and homogeneous areas of suspect asbestos-containing materials (ACM) were visually identified and documented. Although reasonable effort was made to survey accessible suspect materials, additional suspect but un-sampled materials could be located in walls, in voids or in other concealed areas. Suspect ACM samples were collected in general accordance with the sampling protocols outlined in Environmental Protection Agency (EPA) regulation 40 Code of Federal Regulations (CFR) Part 763 (Asbestos Hazard Emergency Response Act, AHERA). Samples were delivered to an accredited laboratory for analysis by polarized light microscopy.

1.1 Project Objective

We understand this asbestos survey was requested due to the planned demolition of the building. EPA regulation 40 CFR 61, Subpart M, National Emission Standards for Hazardous Air Pollutants (NESHAP), prohibits the release of asbestos fibers to the atmosphere during renovation or demolition activities. The asbestos NESHAP requires that potentially regulated ACM (RACM) be identified, classified and quantified prior to planned disturbances or demolition activities.

2.0 BUILDING DESCRIPTION

The building is a single-story, wood framed structure atop a poured concrete floor slab. The exterior is cement plaster finished. The pitched roof is a metal roofing over wood planks. Interior walls consisted of gypsum wallboard with a painted textured finish. The concrete floors are finished with vinyl sheet flooring and yellow adhesive, and carpet. The restroom area was finished with ceramic floor tiles. Ceilings throughout the approximately 1,400 square foot building were finished with drywall, textured and painted with the exception of the kitchen area, which was finished with 9x9 ceiling tiles. Lathe and plaster was present beneath the interior

Asbestos Survey

Proposed Circle K ■ Flora Vista, New Mexico
January 29, 2014 ■ Terracon Project No. 66137030



drywall walls. The air conditioning system consisted of a swamp cooler mounted on the roof. The building construction date and any subsequent renovation dates are unknown.

3.0 FIELD ACTIVITIES

The survey was conducted by Julie Smith, an AHERA-accredited asbestos inspector. A copy of Julie Smith's asbestos inspector training certificate is attached as Appendix D. The survey was conducted in general accordance with the sample collection protocols established in EPA regulation 40 CFR 763, the Asbestos Hazard Emergency Response Act (AHERA). A summary of survey activities is provided below.

3.1 Visual Assessment

Our survey activities began with visual observation of the interior and exterior of the building to identify homogeneous areas of suspect ACM. A homogeneous area consists of building materials that appear similar throughout in terms of color and texture. Interior assessment was conducted throughout visually accessible areas of the building. The exterior survey included an assessment of the exterior walls and roof.

3.2 Physical Assessment

A physical assessment of each homogeneous area of suspect ACM was conducted to assess the friability and condition of the materials. A friable material is defined by the EPA as a material which can be crumbled, pulverized or reduced to powder by hand pressure when dry. Friability was assessed by physically touching suspect materials.

3.3 Sample Collection

Based on results of the visual observation, bulk samples of suspect ACM were collected in general accordance with AHERA sampling protocols. Random samples of suspect materials were collected in each homogeneous area. Sample team members collected bulk samples using wet methods as applicable to reduce the potential for fiber release. Samples were placed in sealable containers and labeled with unique sample numbers using an indelible marker.

Thirty-eight (38) bulk samples were collected from twelve (12) homogeneous areas of suspect ACM. A summary of suspect ACM samples collected during the survey is included as Appendix A.

Asbestos Survey

Proposed Circle K ■ Flora Vista, New Mexico

January 29, 2014 ■ Terracon Project No. 66137030



3.4 Sample Analysis

Bulk samples were submitted under chain of custody to International Asbestos Testing Laboratories (iATL) of Mount Laurel, New Jersey for analysis by polarized light microscopy per EPA methodology EPA/600/R-93/116. The percentage of asbestos, where applicable, was determined by microscopic visual estimation or point counting. iATL is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP Accreditation No. 101165-0).

4.0 REGULATORY OVERVIEW

The asbestos NESHAP (40 CFR Part 61, Subpart M) regulates asbestos fiber emissions and asbestos waste disposal practices. It also requires the identification and classification of existing materials prior to demolition or renovation activity. Under NESHAP, ACM are classified as either friable, Category I non-friable or Category II non-friable ACM. Friable materials are those that, when dry, may be crumbled, pulverized or reduced to powder by hand pressure. Category I non-friable ACM includes packings, gaskets, resilient floor coverings and asphalt roofing products containing more than 1% asbestos. Category II non-friable ACM are any materials other than Category I materials that contain more than 1% asbestos.

Friable ACM, along with Category I and Category II non-friable ACM which is in poor condition and has become friable or which will be subjected to drilling, sanding, grinding, cutting or abrading and which could be crushed or pulverized during anticipated renovation or demolition activities are considered regulated ACM (RACM).

The Occupational Safety and Health administration (OSHA) Asbestos standard for construction (29 CFR 1926.1101) regulates workplace exposure to asbestos. The OSHA standard requires that employee exposure to airborne asbestos fibers be maintained below 0.1 asbestos fibers per cubic centimeter of air (0.1 f/cc) as an eight hour time weighted average. The OSHA standard classifies construction and maintenance activities which could disturb ACM, and specifies work practices and precautions which employers must follow when engaging in each class of regulated work. States which administer their own federally-approved state OSHA programs may require additional precautions.

5.0 FINDINGS AND RECOMMENDATIONS

Laboratory analysis confirmed the presence of friable asbestos-containing materials. A summary of the classification, condition and approximate quantity of confirmed ACM are presented in Appendix B. Laboratory analytical reports are included in Appendix C.

Asbestos Survey

Proposed Circle K ■ Flora Vista, New Mexico

January 29, 2014 ■ Terracon Project No. 66137030



Laboratory analysis confirmed the presence of asbestos in wall and ceiling surfacing texture of the residence and vinyl sheet flooring (linoleum) in the storage garage.

The asbestos-containing wall and ceiling texture in the residence and vinyl sheet flooring in the storage garage are considered RACM and must be removed by a qualified asbestos abatement contractor prior to demolition of the structure in should be in accordance with a project design prepared by a/an accredited/licensed/certified project designer. Licensed asbestos abatement contractors should be contacted to obtain competitive bids for removal of the wall texture within the residence and the vinyl sheet flooring in the storage garage.

6.0 GENERAL COMMENTS

This asbestos survey was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same locale. The results, findings, conclusions and recommendations expressed in this report are based on conditions observed during our survey of the building. The information contained in this report is relevant to the date on which this survey was performed, and should not be relied upon to represent conditions at a later date. This report has been prepared on behalf of and exclusively for use by Circle K Stores, Inc. for specific application to their project as discussed. This report is not a bidding document. Contractors or consultants reviewing this report must draw their own conclusions regarding further investigation or remediation deemed necessary. Terracon does not warrant the work of regulatory agencies, laboratories or other third parties supplying information which may have been used in the preparation of this report. No warranty, express or implied is made.

APPENDIX A

ASBESTOS SURVEY SAMPLE SUMMARY

Sample Log

–Bulk Asbestos –

Client: Terracon Project: 66137030

Sampling Date/Time: 1/14/2014, 11:00am

Bulk Asbestos Sample Log			
Client Sample #	iATL #	Location/Description	Notes
1-01		9"x9" ceiling tiles	
1-02		"	
1-03		"	
2-04		interior plaster, kitchen	
2-05		interior plaster , laundry room	
2-06		interior plaster, kitchen	
3-07		small beaded texture, front bedroom	
3-08		small beaded texture, front bedroom	
3-09		small beaded texture, restroom	
4-10		flat texture, living room	
4-11		flat texture, front end of hallway	
4-12		flat texture, back end of hallway	
4-13		flat texture, laundry room	
4-14		flat texture, living room ceiling	
5-15		linoleum, kitchen	
5-16		linoleum, kitchen doorway to LR	

Sample Log

–Bulk Asbestos–

Client: Terracon Project: 66137030

Sampling Date/Time: 1/14/2014; 11:00am

Bulk Asbestos Sample Log			
Client Sample #	iATL #	Location/Description	Notes
5-17		linoleum, by restroom	under carpet
6-18		drywall/tape, hallway	*composite*
6-19		drywall/tape, laundry room	*composite*
6-20		drywall/tape, living room	*composite*
7-21		Exterior n window caulk	
7-22		Exterior n window caulk	
7-23		Exterior ne window caulk	
8-24		Exterior plaster, ne corner	
8-25		Exterior plaster, nw corner	
8-26		Exterior plaster, sw corner	
9-27		drywall/tape, storage bldg	*composite*
9-28		drywall/tape, storage bldg	*composite*
9-29		drywall/tape, storage bldg	*composite*
10-30		linoleum, storage bldg	
10-31		"	
10-32		"	

APPENDIX B

CONFIRMED ASBESTOS-CONTAINING MATERIALS

**Proposed Circle K Store
SWC of Highway 516 and County Road 350
Flora Vista, New Mexico**

SAMPLE NO.	DESCRIPTION	MATERIAL LOCATION	PERCENT/TYPE ASBESTOS	NESHAP CLASSIFICATION	CONDITION	ESTIMATED QUANTITY
2-05	Tan Texture	Laundry room walls and ceiling	PC 1.1 Chrysotile	Friable	Good condition	300 ft ²
4-10	White flat texture	Walls and ceiling throughout interior of residence	PC 1.2 Chrysotile	Friable	Good Condition	2,600 ft ²
4-11			PC 1.1 Chrysotile			
4-12			PC 1.1 Chrysotile			
4-13			PC 1.4 Chrysotile			
4-14			PC 1.3 Chrysotile			
10-30	Tan vinyl sheet flooring	Storage garage floor	35% Chrysotile	Friable	Poor Condition	130 ft ²
10-31			35% Chrysotile			
10-32			35% Chrysotile			

PC = point count

ft² = square feet

Friable = any material containing more than 1 percent asbestos as determined using Polarized Light Microscopy (PLM), that, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. If the asbestos content is less than 10 percent as determined by a method other than point county by PLM, verify the asbestos content by point counting using PLM.

APPENDIX C

ASBESTOS LABORATORY ANALYTICAL REPORTS

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210362	Description / Location: Brown Ceiling Tile; 9x9
Client No.: 1-01	
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
98	Cellulose
<u>% Non-Fibrous Material</u>	
	2

Lab No.: 5210363	Description / Location: Brown Ceiling Tile; 9x9
Client No.: 1-02	
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
98	Cellulose
<u>% Non-Fibrous Material</u>	
	2

Lab No.: 5210364	Description / Location: Brown Ceiling Tile; 9x9
Client No.: 1-03	
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
98	Cellulose
<u>% Non-Fibrous Material</u>	
	2

Lab No.: 5210365	Description / Location: Tan Plaster
Client No.: 2-04	Interior, Kitchen
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
1	Hair
<u>% Non-Fibrous Material</u>	
	99

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:


EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Approved By:



Date: 1/22/2014

Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210366	Description / Location: White Plaster
Client No.: 2-05	Interior, Laundry Room
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210366	Description / Location: Tan Texture	Layer No.: 2
Client No.: 2-05	Interior, Laundry Room	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
PC 1.1	Chrysotile	PC 97.9
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
	Cellulose	

Lab No.: 5210367	Description / Location: White Plaster
Client No.: 2-06	Interior, Kitchen
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210367	Description / Location: Tan Plaster	Layer No.: 2
Client No.: 2-06	Interior, Kitchen	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	100
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
Trace	Hair	

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210368	Description / Location: White Texture
Client No.: 3-07	Front Bedroom
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210369	Description / Location: White Texture
Client No.: 3-08	Front Bedroom
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210370	Description / Location: White Texture
Client No.: 3-09	Restroom
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210371	Description / Location: Off-White Texture
Client No.: 4-10	Living Room
<u>% Asbestos</u>	<u>Type</u>
PC 1.2	Chrysotile
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	PC 98.8

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government.
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client:	Terracon Environmental Inc	Report Date:	1/23/2014
	4905 Hawkins St NE	Report No.:	323479
	Albuquerque NM 87109	Project:	Circle K
		Project No.:	66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.:	5210372	Description / Location:	Off-White Texture
Client No.:	4-11		Front End Of Hallway
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
PC 1.1	Chrysotile	None Detected	None Detected
			<u>% Non-Fibrous Material</u>
			PC 98.9

Lab No.:	5210373	Description / Location:	Off-White Texture
Client No.:	4-12		Back End Of Hallway
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
PC 1.1	Chrysotile	None Detected	None Detected
			<u>% Non-Fibrous Material</u>
			PC 98.9

Lab No.:	5210374	Description / Location:	Off-White Texture
Client No.:	4-13		Laundry Room
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
PC 1.4	Chrysotile	None Detected	None Detected
			<u>% Non-Fibrous Material</u>
			PC 98.6

Lab No.:	5210375	Description / Location:	Off-White Texture
Client No.:	4-14		Living Room Ceiling
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
PC 1.3	Chrysotile	None Detected	None Detected
			<u>% Non-Fibrous Material</u>
			PC 98.7

Accreditations: NIST-NVLAP No. 101165-0 NY-DOH No. 11021 AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method: EPA 600/R-93/116, by Polarized Light Microscopy

Comments: Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210376	Description / Location: Tan Vinyl Sheet Flooring
Client No.: 5-15	Kitchen
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
15	Cellulose
1	Fibrous Glass
<u>% Non-Fibrous Material</u>	84

Lab No.: 5210376	Description / Location: Tan Mastic	Layer No.: 2
Client No.: 5-15	Kitchen	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	100
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
None Detected	None Detected	

Lab No.: 5210376	Description / Location: Grey Vinyl Sheet Flooring	Layer No.: 3
Client No.: 5-15	Kitchen	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	80
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
20	Cellulose	

Lab No.: 5210376D	Description / Location: Off-White Mastic
Client No.: 5-15	Kitchen
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Accreditations: NIST-NVLAP No. 101165-0 NY-DOH No. 11021 AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method: EPA 600/R-93/116, by Polarized Light Microscopy

Comments: Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210377	Description / Location: Tan Vinyl Sheet Flooring			
Client No.: 5-16	Kitchen Doorway To LR			
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	15	Cellulose	84
		1	Fibrous Glass	
Lab No.: 5210377	Description / Location: Tan Mastic			
Client No.: 5-16	Kitchen Doorway To LR			
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	None Detected	None Detected	100
Lab No.: 5210377	Description / Location: Grey Vinyl Sheet Flooring			
Client No.: 5-16	Kitchen Doorway To LR			
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	30	Cellulose	70

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210378	Description / Location: Tan Vinyl Sheet Flooring	
Client No.: 5-17	By Restroom Under Carpet	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>
None Detected	None Detected	15
		1
		Cellulose
		Fibrous Glass
		84

Lab No.: 5210378	Description / Location: Tan Mastic	Layer No.: 2
Client No.: 5-17	By Restroom Under Carpet	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>
None Detected	None Detected	None Detected
		None Detected
		100

Lab No.: 5210378	Description / Location: Grey Vinyl Sheet Flooring	Layer No.: 3
Client No.: 5-17	By Restroom Under Carpet	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>
None Detected	None Detected	30
		Cellulose
		70

Lab No.: 5210379	Description / Location: White/Tan Sheetrock Off-White Jt Compound	
Client No.: 6-18	Composite; Hallway	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>
PC Trace	Chrysotile	3
		Cellulose
		97

Accreditations: NIST-NVLAP No. 101165-0 NY-DOH No. 11021 AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method: EPA 600/R-93/116, by Polarized Light Microscopy

Comments: Quantification at $\leq 0.25\%$ by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client:	Terracon Environmental Inc	Report Date:	1/23/2014
	4905 Hawkins St NE	Report No.:	323479
	Albuquerque NM 87109	Project:	Circle K
		Project No.:	66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.:	5210380	Description / Location:	White/Tan Sheetrock Off-White JtCompound	
Client No.:	6-19		Composite; Laundry Room	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
PC Trace	Chrysotile	3	Cellulose	97

Lab No.:	5210380	Description / Location:	Off-White Fibrous	Layer No.:	2
Client No.:	6-19		Composite; Laundry Room		
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>	
None Detected	None Detected	98	Cellulose	2	

Lab No.:	5210381	Description / Location:	White/Tan Sheetrock Off-White JtCompound	
Client No.:	6-20		Composite; Living Room	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
PC Trace	Chrysotile	3	Cellulose	97

Lab No.:	5210382	Description / Location:	Grey/Clear Caulk	
Client No.:	7-21		Exterior N Window	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	None Detected	None Detected	100

Accreditations: NIST-NVLAP No. 101165-0 NY-DOH No. 11021 AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method: EPA 600/R-93/116, by Polarized Light Microscopy

Comments: Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Robb

Date: 1/22/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210383	Description / Location: Grey/Clear Caulk
Client No.: 7-22	Exterior N Window
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	100

Lab No.: 5210384	Description / Location: Grey/Tan Caulk
Client No.: 7-23	Exterior NE Window
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	100

Lab No.: 5210385	Description / Location: Grey Plaster
Client No.: 8-24	Exterior, NE Corner
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	100

Lab No.: 5210385	Description / Location: White Plaster	Layer No.: 2
Client No.: 8-24	Exterior, NE Corner	
<u>% Asbestos</u>	<u>Type</u>	<u>% Non-Fibrous Material</u>
None Detected	None Detected	
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
None Detected	None Detected	
		100

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Clay

Date: 1/23/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210386	Description / Location: Grey Plaster
Client No.: 8-25	Exterior, NW Corner
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	100

Lab No.: 5210387	Description / Location: Grey Plaster
Client No.: 8-26	Exterior, SW Corner
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	100

Lab No.: 5210387	Description / Location: White Plaster	Layer No.: 2
Client No.: 8-26	Exterior, SW Corner	
<u>% Asbestos</u>	<u>Type</u>	
None Detected	None Detected	
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>	
None Detected	None Detected	
<u>% Non-Fibrous Material</u>		
		100

Lab No.: 5210388	Description / Location: Tan Sheetrock; Off-White JtCompound
Client No.: 9-27	Composite; Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
18	Cellulose
<u>% Non-Fibrous Material</u>	
	82

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Clay

Date: 1/23/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210389	Description / Location: Tan Sheetrock;Off-White JtCompound
Client No.: 9-28	Composite; Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
18	Cellulose
<u>% Non-Fibrous Material</u>	
	82

Lab No.: 5210390	Description / Location: Tan Sheetrock;Off-White JtCompound
Client No.: 9-29	Composite; Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
18	Cellulose
<u>% Non-Fibrous Material</u>	
	82

Lab No.: 5210391	Description / Location: Tan Vinyl Sheet Flooring
Client No.: 10-30	Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
35	Chrysotile
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	65

Lab No.: 5210392	Description / Location: Tan Vinyl Sheet Flooring
Client No.: 10-31	Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
35	Chrysotile
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	
	65

Accreditations: NIST-NVLAP No. 101165-0 NY-DOH No. 11021 AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method: EPA 600/R-93/116, by Polarized Light Microscopy

Comments: Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Clay

Date: 1/23/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.:	5210393	Description / Location:	Tan Vinyl Sheet Flooring Storage Bldg.	
Client No.:	10-32			
% Asbestos	Type	% Non-Asbestos Fibrous Material	Type	% Non-Fibrous Material
35	Chrysotile	None Detected	None Detected	65

Lab No.:	5210394	Description / Location:	Off-White Texture Wall, Storage Bldg.	
Client No.:	11-33			
% Asbestos	Type	% Non-Asbestos Fibrous Material	Type	% Non-Fibrous Material
None Detected	None Detected	None Detected	None Detected	100

Lab No.:	5210395	Description / Location:	Off-White Texture Wall, Storage Bldg.	
Client No.:	11-34			
% Asbestos	Type	% Non-Asbestos Fibrous Material	Type	% Non-Fibrous Material
None Detected	None Detected	None Detected	None Detected	100

Lab No.:	5210396	Description / Location:	Off-White Texture Wall, Storage Bldg.	
Client No.:	11-35			
% Asbestos	Type	% Non-Asbestos Fibrous Material	Type	% Non-Fibrous Material
None Detected	None Detected	None Detected	None Detected	100

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Clay

Date: 1/23/2014

CERTIFICATE OF ANALYSIS

Client: Terracon Environmental Inc
4905 Hawkins St NE
Albuquerque NM 87109

Report Date: 1/23/2014
Report No.: 323479
Project: Circle K
Project No.: 66137030

BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 5210397	Description / Location: Off-White Glazing
Client No.: 12-36	Window, Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210398	Description / Location: Off-White Glazing
Client No.: 12-37	Window, Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Lab No.: 5210399	Description / Location: Off-White Glazing
Client No.: 12-38	Window, Storage Bldg.
<u>% Asbestos</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Asbestos Fibrous Material</u>	<u>Type</u>
None Detected	None Detected
<u>% Non-Fibrous Material</u>	100

Accreditations:

NIST-NVLAP No. 101165-0

NY-DOH No. 11021

AIHA-LAP, LLC No. 100188

*This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA or any agency of the U.S. government
This report shall not be reproduced except in full, without written approval of the laboratory.*

Analytical Method:

EPA 600/R-93/116, by Polarized Light Microscopy

Comments:

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analysis Performed By: S. Clay

Date: 1/23/2014

APPENDIX D

CERTIFICATIONS

FIELD SCIENCES INSTITUTE

CERTIFIES THAT

JULIE SMITH

HAS SUCCESSFULLY COMPLETED THE REQUIRED
TRAINING FOR ACCREDITATION UNDER TSCA TITLE II

**4 HOUR
ASBESTOS INSPECTOR
REFRESHER**

Date of Course: 11/13/2013



Instructor

Expiration Date: 11/13/2014

CERTIFICATE NUMBER: IR131113006

***FSI* FIELD SCIENCES INSTITUTE**